

**Order your Spare Parts here -> <http://www.lichtboxx.com/index.php/cPath/158/language/en>
www.lightspares.com | ©MS Lichttechnik GmbH, Hirschstettner Strasse 19A, 1220-Vienna, Austria**

Spare Parts List of Martin RUSH MH 3 Beam

50480503	Foot pad
50480504	Fast-locking buckle
50480505	Handle
50480507	Front/back cover
50480508	Left/right cover
50480526	Plastic yoke cover
50480529	Optical orientation plate
50480534	Display Assembly
50480535	Connection assembly
50480536	Switch power supply
50480537	Ballast for RUSH MH3
50480538	Rolling fan
50480539	Lens assembly
50480540	Gobo and color wheel assembly
50480541	Head cover assembly
50480542	Lens cover
50480543	Lens glass
50480544	Timing belt B67MXL
50480545	Belt
50480546	MSD Platinum 5R
50480547	Temperature switch
50480548	Turbo fan
50480549	Rolling fan
50480550	Spindle core assembly
50480551	Timing belt
50480552	Pan axis
50480553	Beam vice board D
50480554	Beam vice board C
50480555	Rolling fan
50480556	Self-locking assembly
50480557	Step motor
50480558	Hall-element board F
50480559	Synchronous belt for pan
50480565	POWERCON socket
50480567	Crossing insurance seat
50480568	DMX 3pin and 5pin transmit board
50480589	Beam driver board MH3
50480634	Step motor MH 4
50480638	PSU 400W MH 3
50480642	Female Quarter turn
50480766	Cover with safety Label MH 3
50480771	Focus plate MH 3
50480772	Sliderods for Focus MH3

50480778	Display board MH 3
50480779	Eight facet prism MH 3
50480780	Frost glass for MH 3
50480781	Frost motor MH 3
50480782	Motor MH 3
50480783	Color wheel MH 3
50480784	RUSH logo plate with glue
50480785	Head cover MH 3 with text
50480833	Tilt motor MH 3
50480835	MH3 gobo motor
50480919	HEAT GLASS MH 3

**Order your Spare Parts here -> <http://www.lichtboxx.com/index.php/cPath/158/language/en>
www.lightspares.com | ©MS Lichttechnik GmbH, Hirschstettner Strasse 19A, 1220-Vienna, Austria**